Boring Diagram Explanation





(Not drawn to scale)