

# Boring Diagram Explanation

Amount of Water Vapor That Will Saturate  
1 Cubic Meter of Air at Different Temperatures

Air Temperature (°C)	Water Vapor (g/m <sup>3</sup> )
-20	1
-10	2
0	5
10	9
20	17
30	29
40	50

